


<b>macpherson</b>		
Product <b>AXIA Install Version</b>		
Drawing No. <b>70628</b>	Page <b>01 of 03</b>	Date <b>04/22/03</b>
<a href="http://www.macpherson-inc.com">www.macpherson-inc.com</a>		


### Overhead Suspension Back Hang Plate

Material: 0.250" Steel  
 Holes: 0.343" (3 places)



### Overhead Suspension Front Flybar

Material: 0.188" Steel Tubing; 0.375" Steel (Top); 0.250" Steel (Sides)  
 Holes: 0.390" (2 places)




<b>macpherson</b>		
Product <b>AXIA Install Version</b>		
Drawing No. <b>70628</b>	Page <b>02 of 03</b>	Date <b>04/22/03</b>
<a href="http://www.macpherson-inc.com">www.macpherson-inc.com</a>		

### Cabinet-to-Cabinet Side Link Plate

Material: 0.250" Steel


Holes: 0.390" (8 places)



### Cabinet-to-Cabinet Link Hinge

Material: 0.120" Steel

Holes: 0.343" (6 places)



**macpherson**

Product **AXIA Install Version**

Drawing No. **70628**

Page **03 of 03**

Date **04/22/03**

[www.macpherson-inc.com](http://www.macpherson-inc.com)