



Parts Summary

Product	Page
KS1152
KS2183
MS18.4
MD18.5
SCHOLAR Model 1186
M10P/M10PF7
M12B/M12BP8
M12C/M12CP9
M12X/M12XP	10
PC12	11
Monolith (Original Version)	12
Monolith Version 2	13
M1/M1S	14
AXIA	15
M15X.	16
LPX (Original Version)	17
LPX Version 2.	18
M2B (Original Version).	19
M2B Version 2	20
M2X (Original Version).	21
M2X Version 2	22
M2XP Version 2	23
IS12	24
IS12X.	25
IS15	26
IS15X.	27
LFE12	28

KS115 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80294*	Woofers Assembly, 15 inch	EVM (Russia) B254C26-8	80293
This woofer is no longer available; EVM is no longer in operation. No reconing options available. Replace with MacPherson part number 80414.			
or 80414**	Woofers Assembly, 15 inch	Selenium 15SWS1100	80413
The above is an update of original part; Selenium 15SW1P (Same MacPherson part numbers.)			
80415	Recone Kit for 15SWS1100	Selenium RPW15SWS1100	

Notes:

* 80294 has bolt circle of 375 mm.
** 80414 has bolt circle of 368 mm (woofer mounting holes can be filed to allow installation in cabinets designed for 80294). Baffle cutout 351 mm.

KS218 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80417	Woofer Assembly, 18 inch (Qty. 2 per KS218)	Selenium 18SWS800	80416
The above is an update of original part; Selenium 18SW2P; MacPherson part number 80401.			
80418	Recone Kit for Selenium 18SWS800	Selenium RPW18WS800	
80419	Recone Kit for Selenium 18SW2P	Selenium RPW18SW2P	

Notes:

MS18 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80417	Woofer Assembly, 18 inch	Selenium 18SWS800	80416
The above is an update of original part; Selenium 18SW2P; MacPherson part number 80401.			
80418	Recone Kit for Selenium 18SWS800	Selenium RPW18WS800	
80419	Recone Kit for Selenium 18SW2P	Selenium RPW18SW2P	

Notes:

MS18 units originally used Electro-Voice EVX180/EVX180A/EVX180B; MacPherson part number 80243.

MD18 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80266	Woofers Assembly, 18 inch (Qty. 2 per MD18)	Radian 2218	80265
The above is an update of original part; Electro-Voice EVX180/EVX180A/EVX180B; MacPherson part number 80243.			
80268	Recone Kit for Radian 2218	Radian RK2218	

Notes:

SCHOLAR Model 118 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80266	Woofers Assembly, 18 inch	Radian 2218	80265
80268	Recone Kit for Radian 2218	Radian RK2218	

Notes:

M10P/M10PF Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80406	Woofers Assembly, 10 inch	Selenium 10PW3	80405
80421	HF Driver Assembly, 1 inch	Selenium D220Ti-8	80420
The above is an update of original part; Selenium D210Ti-8; MacPherson part number 80403 (raw part number 80402).			
80422	Replacement Diaphragm for D220Ti-8	Selenium RPD220Ti-8	
80412	Replacement Diaphragm for D210Ti-8	Selenium RPD210Ti-8	
80404	HF Horn	Selenium HM11-25	

Notes:

M12B/M12BP Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80236	Woofers Assembly, 12 inch	B&C 12PS76-8	80204
The above is an update of original part; B&C 12PZ32-8. (Same MacPherson part numbers.)			
80410	HF Driver Assembly, 1 inch	B&C DE160-8	80409
The above is an update of original part; B&C DE16-8; MacPherson part number 80240.			
80411	Replacement Diaphragm for DE160-8	B&C MD/DE160-8	
80251	Replacement Diaphragm for DE16-8	B&C MD/DE16-8	
80224	HF Horn	Selenium HM17-25	

Notes:

M12C/M12CP Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80236	Woofers Assembly, 12 inch	B&C 12PS76-8	80204
The above is an update of original part; B&C 12PZ32-8. (Same MacPherson part numbers.)			
80410	HF Driver Assembly, 1 inch	B&C DE160-8	80409
The above is an update of original part; B&C DE16-8; MacPherson part number 80240.			
80411	Replacement Diaphragm for DE160-8	B&C MD/DE160-8	
80251	Replacement Diaphragm for DE16-8	B&C MD/DE16-8	
80224	HF Horn	Selenium HM17-25	

Notes:

M12X/M12XP Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80236	Woofers Assembly, 12 inch	B&C 12PS76-8	80204
The above is an update of original part; B&C 12PZ32-8. (Same MacPherson part numbers.)			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

Suggested fitting for overhead suspension applications is New Haven NH47556-11, black; MacPherson part number 80589.
Possible alternatives include Kinedyne 32501 and 32502; Cargo Equipment Corp. CE32501 and CE32502.

PC12 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80248	Woofer Assembly, 12 inch	B&C 12PLB76-8	80247
The above is an update of original part; B&C 12PL32-8. (Same MacPherson part numbers.)			
80271	HF Driver Assembly, 1 inch	Beyma CP-380/M-8	80270
80282	Replacement Diaphragm for CP-380/M-8		

Notes:

Monolith (Original Version) Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80291	Woofers Assembly, 18 inch	Electro-Voice DL18MT	80209
The above is an update of original part; Electro-Voice 5018MT; MacPherson part number 80232.			
80246	MF Driver Assembly, 6.5 inch (Qty. 2 per Monolith)	Audax PR170Z0	80245
The above is an update of original part; Audax PR170M2; MacPherson part number 80230.			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

Recone kit for Audax PR170Z0 is Audax RP170Z0; MacPherson part number 80298.
Suggested fitting for overhead suspension applications is New Haven NH47556-11, black; MacPherson part number 80589.
Possible alternatives include Kinedyne 32501 and 32502; Cargo Equipment Corp. CE32501 and CE32502.

Monolith Version 2 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80291	Woofers Assembly, 18 inch	Electro-Voice DL18MT	80209
The above is an update of original part; Electro-Voice 5018MT; MacPherson part number 80232.			
80246	MF Driver Assembly, 6.5 inch (Qty. 2 per Monolith Version 2)	Audax PR170Z0	80245
The above is an update of original part; Audax PR170M2; MacPherson part number 80230.			
80298	Recone Kit for PR170Z0	Audax RP170Z0	
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

Recone kit for Audax PR170Z0 is Audax RP170Z0; MacPherson part number 80298.
Suggested fitting for overhead suspension applications is New Haven NH47556-11, black; MacPherson part number 80589.
Possible alternatives include Kinedyne 32501 and 32502; Cargo Equipment Corp. CE32501 and CE32502.

M1/M1S Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
-----	Woofers, 15 inch	Electro-Voice DL15ST	-----
The above is an update of original part; Electro-Voice EVM15B.			
-----	MF Driver Assembly, 6.5 inch (Qty. 2 per M1S)	Audax PR17HR70 or PR170M2	-----
Acceptable substitute for above is Audax PR170Z0.			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	-----
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

Some very early M1S units used Radian 1 inch HF drivers. Replacement diaphragms may be available from Radian.

AXIA Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80263	Woofers Assembly, 15 inch	Radian 2216-8	80262
80267	Recone Kit for Radian 2216-8	Radian RK2216-8	
80256	MF Driver Assembly, 8 inch (Qty. 2 per AXIA)	B&C 8TC21-16	80260
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

M15X Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80276	Woofers Assembly, 15 inch	Beyma 15LX60	80275
The above is an update of original part; Electro-Voice EVX150/EVX150A/EVX155; MacPherson part number 80237.			
80299	Recone Kit for 15LX60		
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

Suggested fitting for overhead suspension applications is New Haven NH47556-11, black; MacPherson part number 80589.
Possible alternatives include Kinedyne 32501 and 32502; Cargo Equipment Corp. CE32501 and CE32502.

LPX (Original Version) Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80237	Woofers Assembly, 15 inch	Electro-Voice EVX150/EVX150A/EVX155	80275
Reconing may be available from Electro-Voice or other 3rd parties.			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

LPX Version 2 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80276	Woofers Assembly, 15 inch	Beyma 15LX60	80275
80299	Recone Kit for 15LX60		
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

M2B (Original Version) Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80214	Woofers, 15 inch	Electro-Voice EVM15L	80275
This woofer is no longer available, having been made obsolete by Electro-Voice. Reconciling may be available from Electro-Voice or other 3rd parties.			
80202	HF Driver, 1 inch	B&C DE25-16	
80203	Replacement Diaphragm for DE25-16	B&C MD/DE25-16M	

Notes:

Early production M2B units used HF driver B&C DE24-16. Direct replacement is B&C DE25-16.

M2B Version 2 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80286	Woofers Assembly, 15 inch	EVM (Russia) B154C15-8	80285
80297	Replacement Woofers Frame Assembly for B154C15-8		
80287	HF Driver Assembly, 1 inch	B&C DE25-8	80283
80284	Replacement Diaphragm for DE25-8	B&C MD/DE25-8	

Notes:

M2X (Original Version) Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80237	Woofers Assembly, 15 inch	Electro-Voice EVX150/EVX150A/EVX155	80285
Reconing may be available from Electro-Voice or other 3rd parties.			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

M2X Version 2 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80263*	Woofers Assembly, 15 inch	Radian 2216-8	80262
80267	Recone Kit for Radian 2216-8	Radian RK2216-8	
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

* 80263 has bolt circle of 370 mm; baffle cutout 355 mm.

M2XP Version 2 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80414	Woofers Assembly, 15 inch	Selenium 15SWS1100 or 15SW1P	80413
80415	Recone Kit for Selenium 15SWS1100	Selenium RPW15SWS1100	
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	

Notes:

IS12 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80248	Woofers Assembly, 12 inch	B&C 12PLB76-8	80247
The above is an update of original part; B&C 12PL32-8. (Same MacPherson part numbers.)			
80410	HF Driver Assembly, 1 inch	B&C DE160-8	80409
The above is an update of original part; B&C DE16-8; MacPherson part number 80240.			
80411	Replacement Diaphragm for DE160-8	B&C MD/DE160-8	
80251	Replacement Diaphragm for DE16-8	B&C MD/DE16-8	

Notes:

IS12X Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80236	Woofers Assembly, 12 inch	B&C 12PS76-8	80204
The above is an update of original part; B&C 12PZ32-8. (Same MacPherson part numbers.)			
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

IS15 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80253	Woofers Assembly, 15 inch	B&C 15PLB76-8	80252
The above is an update of original part; B&C 15PL40-8. (Same MacPherson part numbers.)			
80410	HF Driver Assembly, 1 inch	B&C DE160-8	80409
The above is an update of original part; B&C DE16-8; MacPherson part number 80240.			
80411	Replacement Diaphragm for DE160-8	B&C MD/DE160-8	
80251	Replacement Diaphragm for DE16-8	B&C MD/DE16-8	

Notes:

IS15X Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80263	Woofers Assembly, 15 inch	Radian 2216-8	80262
80267	Recone Kit for Radian 2216-8	Radian RK2216-8	
80228	HF Driver Assembly, 2 inch	Modified B&C DE75PTN-8	80289
The above is an update of original part; B&C DE75P-8; MacPherson part number 80206.			
80290	Replacement Diaphragm for DE75PTN-8 and DE75P-8	B&C MD/DE75TN-8M	
The replacement diaphragm for DE75P-8 was previously B&C MMD75-8; MacPherson part number 80207.			

Notes:

LFE12 Parts Summary

Part No.	Description	Manufacturer Part No.	Raw Part No.
80236	Woofers Assembly, 12 inch	B&C 12PS76-8	80204
The above is an update of original part; B&C 12PZ32-8. (Same MacPherson part numbers.)			

Notes:
